



# EC - CERTIFICATE

Type-Examination No: BSI-LB-009



Category, make and type or trade name: Energy Dissipation Buffer Model LB25-003

Name and address of manufacturer: Oleo International  
Grovelands  
Longford Road  
Exhall  
Coventry CV7 9ND

Name and address of Certificate holder: Oleo International  
Grovelands  
Longford Road  
Exhall  
Coventry CV7 9ND

Date of submission for EEC type-examination: 3 September 1998

Certificate issued on the basis of the following requirement: On the basis of our examination under the requirements of Council Directive 95/16/EC Annex V the Lift Directive, as recorded in BSI Test Report 282/005059-20 dated 21/10/98

Date of type-examination: September - October 1998

Documents bearing the type examination number shown above are annexed to this Certificate: Report Number 282/005059-20

For and on behalf of the BRITISH STANDARDS INSTITUTION,  
Notified Body Number 0086

Signature:  C Cooper (General Manager)

Date: 23/10/98

*Any modification to the design of this product will invalidate this EC-Certificate and the BSI Notified Body Number 0086 must be informed without delay*

Prepared by: BSI Product Services Maylands Avenue Hemel Hempstead  
Hertfordshire HP2 4SQ UK Telephone: 44 1442 230442 Fax: 44 1442 231442





# EC - CERTIFICATE

Type-Examination No: BSI-LB-009



(Continuation Sheet)

## ADDITIONAL INFORMATION

### LIMITATIONS OF CERTIFICATE VALIDITY

This EC Type-Examination Certificate is only valid when an Energy Dissipation Buffer Model LB25-003 is installed under the following conditions:

- 1 At a maximum impact speed of 2.92 m/s.
- 2 With a minimum total mass of 500 kg.
- 3 With a maximum total mass of 8330 kg.
- 4 When filled with hydraulic liquid grade ISO VG 68

For and on behalf of the BRITISH STANDARDS INSTITUTION,  
Notified Body Number 0086

Signature:  C Cooper (General Manager)

Date: 23/10/98

*Any modification to the design of this product will invalidate this EC-Certificate and the BSI Notified Body Number 0086 must be informed without delay*

Prepared by: BSI Product Services Maylands Avenue Hemel Hempstead  
Hertfordshire HP2 4SQ UK Telephone: 44 1442 230442 Fax: 44 1442 231442